

SOMALIA, BU'AALE DISTRICT STATUS OF RIVER BREAKAGES **RIVER JUBA - AUGUST 2021**











Produced by:
The Somalia Water and Land Information Management Project (SWALIM).

SWALIM is a multi-donor project implemented by the United Nation's Food & Agriculture Organization

For copies of digital data please contact: swalim@fao.org

Verified Breakage: Confirmed this season through VHR Images and/ Field Verification

Not Verified Breakage: Confirmed in previous season but there was either cloudy or no VHR Image for assessment this season

Satellite data: WV2/WV3 Imagery dates: Mar 2019 - Aug 2021 Imagery resolution: 0.3 - 0.5 Meter Imagery source: Digital Globe, Airbus Other dataset: FAO-SWALIM, UNDP Analysis: FAO-SWALIM Map projection: Geographic Datum: WGS 84

